

## ENGINEERED SOLUTIONS FOR INDUSTRIES WORLDWIDE

## SOLON® BELLEVILLE SPRINGS | SOLON® PRESSURE SWITCHES

## TECHNICAL SERVICE BULLETIN

**Document No.:** D73321.15

Subject: New Solon Washer Tolerance Scheme

Part Numbers Affected: Solon catalog Belleville washers

**Condition**: Catalog washers have historically been designed with varying tolerance limits for inner diameter (ID), outer diameter (OD), thickness (T), and overall height (OH).

Cause: A universally accepted tolerance was not chosen or available.

**Diagnosis**: The Solon washer catalog does not currently conform to a consistent, standard tolerance scheme.

**Correction**: Starting in September 2020, Solon Manufacturing Company will begin transitioning catalog Belleville washers to tolerance limits defined in International Standard ISO 19690-2. Some custom and DIN spec springs have been excluded from this correction.

Approved By: G. Davet Approved Date: 09-14-2020

Originated By: T. Burg Original Issue Date: 09-14-2020